

# Storm Drainage

Before

After

stormwater



bridges/ culverts

roadways

water



wastewater

civil/ site

development



Chambliss Engineering, LLC

356 Highway 82 W  
Prattville, AL 36067

tel: 334.491.2323  
fax: 334.491.2324

[clyde@chamblissengineering.com](mailto:clyde@chamblissengineering.com)



Town of Elmore  
CDBG Drainage Improvements  
Winter 2003

The project involved ditch cleaning, storm drainage piping, water main relocation, and street resurfacing. The photographs shown on the left were taken before construction, and those on the right were taken after final grading, grassing, and resurfacing. Both sets of photos were taken immediately after an average winter rain storm. Pipes that were sloped incorrectly or installed at an improper elevation were replaced. Ditches were excavated and cleaned to allow proper flow between pipe inverts.